



© 2015

HIGH TORQUE STARTER WIRING DETAIL

Use this diagram for wiring the Starter to prevent starter solenoid contact welding for high torque competition engine starters.

